Doc.No.MIS20J108689(1/1)

Failure Analysis Report

Customer Name: OCT Product Type Name: NS10-TV00B-ECV2 ROS No. : R100728-100 Issue of Date : 23-Aug-10

Manager Hideki Iwanaga (Charge Shinichi Ito) Service Center Industrial Business Service Division Omron Field Engineering Corporation

1. Returned Product information:

Product Type Name	Qty	Product Lot Code	Production Date
NS10-TV00B-ECV2	1	1367K	13-Jun-07

- 2. Customer's description of failure: Touch panel failed.
- 3. Confirmation of failure:

We find a part of touch switch doesn't work.

4. Specifying the cause of failure:

The cause is the failure touch panel (TYPE:TP-3142S2F0). We supposed the cause of this failure was due to humid using condition.

5. Corrective action:

After replacing the failure touch panel, we changed the connector (CN10) for the term of validity expiration. And we performed a series of tests, and verified correct operation.